




Walter Neser


Past: VulPro - South Africa

Present: Freelance – Nature and Parks Authority, Israel





Are power line incidents underestimated?




Major threats to vulture populations in Africa. Ogađa et al, 2016




Remains of 15 Cape Vultures collected under one pole, there were 30 more within 2km on this line, the line was erected in 1984 - Neser 2016

Understanding Power-Lines in South Africa






Cape Vulture observations in SA – SABAP II





Electricity Infrastructure - Eskom




504 Cape Vulture Electrocutions Reported - Eskom
















Most Dangerous Structures, and why?



T-Offs, Transformers, Fuses, Breakers & Termination Poles



"Live" Earthed Perch (no BILL Gap)



Jumpers above perch / not insulated



Arc Horns



Small Phase spacing



Pole Characteristics from 200 Cape Vulture Electrocutions in NW Province, SA


Design Features	No of incidents	Percentage
3 x Pin insulators	148	74%
no BILL Gap	122	66%
Earthed Perch via bonding of insulators	70	35%
Small phase spacing	50	25%

Structure type	No of incidents	Percentage
T-Structure	152	76%
Wishbone	32	16%
Staggered Vertical	15	7.5%
Inverted T	1	0.5%


Path of Electrocution	No of incidents	Percentage
Phase to Earth	140	70%
Phase to Phase	42	21%
Phase to Post (wet)	18	9%

Typical Reactive Mitigation






Inadequate



Installation Errors


(old habits die hard)







Power-Line evolution in South Africa




Safest Strain Poles and T-Offs



Opportunities presented by scheduled maintenance! Take advantage and convert to safer structures


















on Eskom power pylons that now fry at least 10 of these birds every month.

That might not sound like a big number, but it is a cause for alarm when there are believed to be only 4,200 breeding pairs left in Southern

And now the monthly toll of vultures killed or maimed by powerline collisions and electrocution has shot up to at least 28 during April – one of these rare birds killed almost every day – according to the vulture conservation group Vulpro.Vulpro founder Kerri Wolter said most of the latest casualties were Cape vultures, electrocuted in the Eastern Cape and North West.


"The tracedy of this latest unaccentably high tally is that it is nessible to








Proactive Mitigation Strategy Announced in 2016




Bird electrocution sensitivity map using data compiled by the South African Bird Atlas Project (SABAP2) © ESKOM/EWT Partnership, ADU, Birdlife SA

Proactive Mitigation Strategy Announced




Bird electrocution sensitivity map using data compiled by the South African Bird Atlas Project (SABAP2) © ESKOM/EWT Partnership, ADU, Birdlife SA



Model of power line electrocution risk in South Africa for Cape vultures.

Warm colours (red and orange) represent high risk lines while cool colours (blues) represent lower risk lines. C.Howes 2016



Cape Vulture electrocutions reported over the model of power line electrocution risk in South Africa for Cape vultures.

Warm colours (red and orange) represent high risk lines while cool colours (blues) represent lower risk lines. C.Howes 2016

